



GARY R. HERBERT  
Governor  
SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Minerals Inspection Report

Report Date: **June 3 2015**


Reviewed 

Mine Name: Kingston Canyon Rock	Permit Number: <i>S/031/0009</i>	Mine Status: Reclaimed
Operator Name: Utah Div. Wildlife Res. / Stan Beckstrom	Inspection Date: 5/27/2015	Permit Fees: No Fee Req.
Inspector(s): Lynn Kunzler	Inspection Time: 3:00 pm	Bond Amount: \$0
Attendee(s):	Weather:	Bond Escalation:
Inspection Purpose: Routine inspection		Prior Inspection: 6/19/2013

### Conclusions and Recommendations

This site was reclaimed about 3 years ago. The site is clean and stable, there were no safety hazards from mining at the site. Reclamation standards have been met. It is recommended that the operator submit Form MR-SITE (available on DOGM;s website) to close this file.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i> This site was reclaimed prior to June, 2012. There is no bond on this site. The annual permit fee is not required.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i> During reclamation, the site was regraded to blend in with surrounding topography. There is no trash on site. The site is stable with no signs of accelerated erosion.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. <i>Protection of Drainages/Erosion Control</i>	<input type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i>	<input type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i> access roads were reclaimed and seeded.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i> The site was reclaimed prior to the June 19, 2012 inspection. Vegetation has re-established and is about 90% of the surrounding vegetation ground cover.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i> The site is well vegetated with desirable species (no noxious weeds). Vegetation ground cover exceeds the 70% of pre-existing cover success standard.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. <i>Other</i>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Stan Beckstrom, DWR ([stanbeckstrom@utah.gov](mailto:stanbeckstrom@utah.gov))

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M031-Piute/S0310009-kingstonCyn/inspections/insp-05272015.pdf





Mine:

Inspected: 5/27/2015

